

## Higher Safety thanks to Solvent Exchange



The substitution of a solvent in the ink system  
Mara<sup>®</sup> Glass MGL increases application safety.  
Proven properties remain unchanged.

### Improved Labelling

Mara<sup>®</sup> Glass MGL contains the solvent "butyl glycolate" which is labelled with Hazard Statement H 361d ("Suspected of damaging the unborn child"). To ensure safe manufacture and application of the ink, we are replacing this solvent. The result is a significantly improved labelling that provides **additional safety for all users**.

Extensive printing tests in various applications confirm: The properties of the optimally dried ink film, such as adhesion and resistance, are not affected by this change in formulation.

### Date of Change-over

We will start with the change-over on **July 1st, 2025** (week code **527**). The two formulations are mixable to allow a smooth transition.

You will find an additional remark on the label stating

**„Attention: Improved Formula“**

### In the event of any queries, please contact:

Technical Hotline  
Phone: +49 7141 691140  
[technical.hotline@marabu.com](mailto:technical.hotline@marabu.com)